

Work Order ID 149504

Wednesday, August 03, 2016 9:03:50 AM

149504

Page 1

Item ID: D044-715-011

Accept

N900040100Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: R44 Cargo Mirror

Start Date: 7/18/2016 Start Qty: 3.00

3

Cust Item ID:

Required Date: 7/25/2016 Req'd Qty: 3.00

3

Customer:

Reference:

Approvals:

Process Plan:

DAS
21
9-89

Date:

AUG 03 2016

Tooling:

Date:

SPC (Y/N):

Date:

Run Start ***NR1***Stop ***NR2***Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

Draw Nbr

Revision Nbr

D3243

Rev A

IIN-D044-715

Rev A

AUG 05 2016

DAS
6
9-89DAS
21
9-8916-08-05
3

100

Document Control

0.00

100

DC

DOCUMENT CONTROL

Memo

0.00

Doc.Control -USB or Paperwork

Photocopy bluefile & type labels per PPPD044-715-011

CHG003

3x DAS
27
9-89

AUG 3 2016

110

Pick Kit

0.00

110

Packaging

Memo

0.00

Packaging

3 R

DAS
28
9-89

AUG 16 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval Completed By _____ Lead hand / Supervisor Approval Verification _____ QC / QA Coordinator Approval _____		
Description Work Order Deviation				Disposition					
240 15 08-6									
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐							
		OTHER : ☐							

Wednesday, August 03, 2016 9:03:50 AM

Page 2

dm 16/08/30

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date :	Step #:	QTY Effective :		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition			
				Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
OTHER : ☐					

Picklist Print

Wednesday, August 03, 2016 9:03:55 AM

Page 1

Work Order ID: 149504

149504

Parent Item: D044-715-011

D044-715-011

Parent Item Name: R44 Cargo Mirror

Start Date: 7/18/2016

Required Date: 7/25/2016

Start Qty: 3.00

Required Qty: 3.00

Comments: IPP Rev:A04.02.18New issueKJ/JLM
IPP Rev:B 06-04-28 Manufactured on Water Jet JLM
IPP Rev:C 08-06-10 as per ECN1195p DD verified by:EC IPP Rev:D
11.05.04 remove FE-032-EF DD verified by:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3243-041 *D3243-041* Bracket		Manufactured	No			110	Each	3.0000	1	3			PC DAS 28 9-89
				<u>Location</u>				<u>Loc Qty</u>					
				ST486				3					
				142885				3		3			
D1048 *D1048* Clamp		Manufactured	No			110	Each	35.0000	2	6			PC DAS 28 9-89
				<u>Location</u>				<u>Loc Qty</u>					
				GA				35					
				148042				11		6			
				148270				24					
D1049 *D1049* Saddle		Manufactured	No			110	Each	22.0000	2	6			PC DAS 28 9-89
				<u>Location</u>				<u>Loc Qty</u>					
				GA				22					
				145278				2		2			
				148238				20		24			

AUG 16 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date :	Step #:	QTY Effective :		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition			
				Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY			
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐
OTHER : ☐					

Picklist Print

Wednesday, August 03, 2016 9:03:55 AM

Page 2

Work Order ID: 149504

149504

Parent Item: D044-715-011

D044-715-011

Parent Item Name: R44 Cargo Mirror

Start Date: 7/18/2016

Required Date: 7/25/2016

Start Qty: 3.00

Required Qty: 3.00

D2010-104	Manufactured	No	110	Each	3.0000	1	3	
D2010-104								**
ARM								

DAS
27
9-89

Location

Loc Qty

Loc Code

ST351

3

144781

3

3

D2011-101	Manufactured	No	110	Each	19.0000	1	3	
D2011-101								**
Mirror 6"								

DAS
27
9-89

Location

Loc Qty

Loc Code

FG

2

106348

2

ST368

17

146270

17

3

AN3-4A	Purchased	No	110	Each	227.0000	4	12	
AN3-4A								**
Bolt								

DAS
27
9-89

Location

Loc Qty

Loc Code

ST350

227

m134955

227

12

AN526C1032R10	Purchased	No	110	Each	110.0000	4	12	
AN526C1032R10								**
Screw								

DAS
27
9-89

Location

Loc Qty

Loc Code

ST326

100

m135133

100

ST328

10

m133234

10

1

12

AUG 16 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date : _____		Step #: _____		QTY Effective : _____			MRB (QSI042) Approval 		
Description Work Order Deviation				Disposition					
				Completed By _____					
				Lead hand / Supervisor Approval Verification _____					
				QC / QA Coordinator Approval _____					
Root Cause		FAULT CATEGORY							
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐				
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐				
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐				
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐				
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐				
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐				
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐				
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐				
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐				
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐				
Past Expiry Date ☐	Manufacturing Process ☐	OTHER : _____							
Misidentified ☐	Past Due ☐								

Picklist Print

Wednesday, August 03, 2016 9:03:55 AM

Page 3

Work Order ID: 149504

149504

Parent Item: D044-715-011

D044-715-011

Parent Item Name: R44 Cargo Mirror

Start Date: 7/18/2016

Required Date: 7/25/2016

Start Qty: 3.00

Required Qty: 3.00

ALS4-1032-130 AELS4-1032-130 Purchased

No

110

Each

1,549.000

4

AI S4-1032-130

Rivnut

12
X M135 442 PC
DAS 28 9-89

DAS
27
9-89

Location

Loc Qty

Loc Code

FP001

607

M133077

122

M134502

485

ST556

942

M134502

942

NAS1149D0332J

Purchased

No

110

Each

1,530.000

4

NAS1149D0332.J

Washer

12
X M135 046 PC
DAS 28 9-89

DAS
27
9-89

Location

Loc Qty

Loc Code

CA

6

m129682

6

FP001

546

m134848

546

GA

967

m135046

967

ST264

11

m134502

6

m134738

5

AUG 16 2016

DQA: _____ Date: _____

**WORK ORDER NON-CONFORMANCE / UPDATE**


QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
OTHER : _____					



DESIGN <i>CP</i>	DRAWN BY <i>CP</i>	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED <i>[Signature]</i>	APPROVED <i>[Signature]</i>	DRAWING NO. D3243	REV. A SHEET 1 OF 1
DATE 04.01.09		TITLE BRACKET	SCALE 1:2
A	04.01.09	NEW ISSUE	



R0.188 (TYP)



**D3243-1 BEND DETAIL/
D3243-041 ASSEMBLY**
SCALE 1:4

INSTALL
FE-032-EF INSERTS
(4 PLACES)

2.75^{+0.030}_{0.000}

NO. 149504 M3
16-07-27
WORK ORDER
UNCONTROLLED COPY
RETURN TO
ENGINEERING
SUBJECT TO AMENDMENT
WITHOUT NOTICE

RELEASED
04-02-03

8.581
8.206
7.706

GRAIN
DIRECTION

11.920
11.420
Ø0.201
(TYP 4
PLACES)

Ø0.290
(TYP 4
PLACES)

1.375
5.273

4.214

R0.25 (TYP)

3.339

R0.38
(TYP)

5.494

R2.75
(TYP)

3.714

**D3243-1
FLAT PATTERN**

R0.50
(TYP)

0.500
0.000

6.560
5.810
5.360

0.750
0.500
0.000

**D3243-041 BRACKET ASSEMBLY
(D3243-1 BRACKET)**

- 1) MATERIAL: 6061-T6, 0.063 THICK
(QQ-A-250/11, REF DART SPEC
M6061T6S.063)
- 2) FINISH: CHEMICAL CONVERSION COAT
PER DART QSI 005 4.1
POWDER COAT BLACK (4.3.5.7) PER
DART QSI 005 4.3
- 3) BREAK ALL SHARP EDGES 0.005 TO
0.010
- 4) ALL DIMENSIONS ARE IN INCHES
- 5) TOLERANCES ARE PER DART QSI 018
UNLESS OTHERWISE NOTED

Copyright © 2004 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Work Order ID 149504

149504

Page 1

Wednesday, August 03, 2016 9:03:50 AM

Item ID: D044-715-011 Accept ***N900040100*** Setup Start ***NS1***
 Revision ID: Stop ***NS2***
 Item Name: R44 Cargo Mirror

Start Date: 7/18/2016 Start Qty: 3.00 ***3*** Cust Item ID:
 Required Date: 7/25/2016 Req'd Qty: 3.00 ***3*** Customer:

Reference:

Approvals: Process Plan: DAS 21 Date: AUG 03 2016 Tooling: Date: Run Start ***NR1***
 QC: 9-89 Date: AUG 03 2016 SPC (Y/N): Date: Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
D3243	Rev A	AUG 05 2016	DAS	6					
IIN-D044-715	Rev A		9-89						
100	Document Control	0.00							
100	DOCUMENT CONTROL	0.00							
DC	Memo								
Doc.Control -USB or Paperwork	Photocopy bluefile & type labels per PPPD044-715-011				CHG003				
110	Pick Kit	0.00							
110		0.00							
Packaging	Memo								
Packaging									

DAS
21
9-89

AUG 05 2016

3

2. GENERAL NOTES

COMPATIBILITY

Compatibility of this installation with the aircraft is the **responsibility of the installer**. Ensure that this installation does not conflict with a previous modification.

CONTINUING AIRWORTHINESS

This installation should be maintained in accordance with the Instructions for Continued Airworthiness ICA-D044-715.

3. INSTALLATION INSTRUCTIONS

To install the Dart Cargo Mirror Installation on the R44 skidtube:

1. Locate the D3243-041 Bracket with approximately 0.38" (10mm) space between the top of the skidtube and the bracket, as shown in Figure 2. Transfer drill the 4 holes from the bracket to the centerline of skidtube and enlarge to 10/64" (Ø0.297"). Deburr holes and wet install ALS7-1032-130 inserts using MIL-P-85582 or MIL-P-23377 primer.
2. Install the D3243-041 Bracket on the skidtube using the AN3 hardware. The bolts should be sealed with Sikaflex-241/-291 or Proseal 890 or MIL-S-8802 Class 'B2' sealant before installing as per Figure 2.
3. Install remaining hardware per Figure 2 as required. Adjust the angle of the D2010-104 Arm and tighten the AN526C1032R10 screws to secure arm.
4. To adjust the mirror: loosen (DO NOT REMOVE) the three adjustment screws shown in Figure 2, reposition the mirror, then tighten the screws.

4. WEIGHT AND BALANCE

Installation	Weight	LATERAL		LONGITUDINAL	
		Arm	Moment	Arm	Moment
D044-715-011 Cargo Mirror Installation	1.3 lb 0.59 kg	41.7 in 1.06 m	54.2 lb-kG 0.63 m-kG	32.0 in 0.81 m	41.6 in-lb 0.48 m-kG

5. PARTS LIST

Qty	Part Number	Description
X	D044-715-011	CARGO MIRROR INSTALLATION
2	D1048	Clamp
2	D1049	Saddle
1	D2010-104	Arm
1	D2011-101	Mirror
1	*D3014-1	Locknut
1	D3243-041	Bracket
4	ALS7-1032-130	Insert (or AKS7-1032-130, AKS4-1032-130, ALS4-1032-130)
4	AN3-4A	Bolt
4	AN526C1032R10	Screw (or AN526-1032R10)
4	AN960JD10L	Washers
1	*AN960JD416L	Washer

* PARTS ARE INCLUDED WITH D2011-101 MIRROR